PANAMETRICS Ultrasonic Flowmeter Training

This training covers the use of the Panametrics ultrasonic flowmeter model No. PT868 and the model No.24 transducer.

1.	Power up the flowmeter and program it to measure ½" S.S. tubing with a wall	
	thickness of .035" Measure Flow:	g.p.m.
2.	Program the flowmeter to measure 3/4" S.S. tubing with a wa	all thickness of .049"
	Measure Flow:	g.p.m.
3.	Recall from memory the program for measuring 1-1/2" S.S. S	* *
	Measure Flow:	g.p.m
Traini	ng given to: MIKE John sow	Date: 8 3 05
Traini	ng given by: Michael Ferry	Date: 2-23-09